



## CONSUMER NOTICE

### STOP PRODUCT USE

#### BUOYANCY COMPENSATOR INFLATORS

AERIS has been informed by its supplier that they have received isolated reports of BC Inflator mechanisms exhibiting continual flow of air into the BC after release of the power inflation button. Affected are AERIS AW3 model Inflators that are fitted on ATMOS XT BCs that were sold between May 1, 2004, and June 24, 2004. BCs sold prior to May 1, 2004, do not have these Inflators and are not affected.

Testing and evaluation has shown that the Power Inflator Button may stick in the depressed position. Engineers have designed new replacement parts that will prevent the Button from sticking.

AERIS asks that all owners of AERIS XT BCs that have AW3 Inflators return them to an Authorized AERIS Dealer for a retrofit at no charge.

**WARNING: DO NOT CONTINUE USE of the BC or attempt to disassemble any components of the Inflator. Take the BC with Inflator to your nearest Authorized AERIS Dealer for inspection and service. Only Authorized AERIS Dealers and their trained service technicians must perform this retrofit. Non-authorized personnel who attempt the retrofit procedure risk voiding the product's warranty and rendering the product dangerously unsafe for normal SCUBA use.**

Thank you for your cooperation.

Sincerely,

AERIS Technical Support



AERIS AW3 style  
BC Power Inflator